


Multimeter Basics and Application Jonah Bailey GEARS 2023




A Few Safety Notes



- Never work on high voltage DC or any AC systems unless qualified
- This class doesn't qualify you
- Don't work on live systems if possible
- Don't work alone
- Unsure? Stop
- Did I mention this course doesn't make you an electrician?



Manual Range





Auto Range





The DMM is your best friend and a good one can be had for about \$50



Ċ

Extech EX330 Autoranging Mini Multimeter with NCV and Type K Temperature, orange and

green

Brand: Extech

***** ~ 824 ratings

-8% ^{\$}54⁹⁹

List Price: \$59.99 🔴

√prime

& FREE Returns ~

or 3 monthly payments ~ of \$18.33

Get 5% back (\$2.74 in rewards) on the amount charged to your Amazon Prime Rewards Visa Signature Card.

May be available at a lower price from other sellers, potentially without free Prime shipping.

Size: Autorange Multimeter with Thermometer

Autorange Multimeter with Thermometer	Electrical TRMS Multimeter
\$54.99	\$109.99
√prime	vprime
Manual Range Multimeter	Standard Autorange
	Multimeter
\$34.22	1 option from \$182.80



You can go as crazy as you want depending upon the features you need



Fluke 117 Digital Multimeter, Non-Contact AC Voltage Detection, Measures Resistance/Continuity/Frequency/Capac itance/Min Max Average, Automatic AC/DC Voltage Selection, Low Impedance Mode Visit the Fluke Store ****** • 3.299 ratings

-10% \$23999

List Price: \$265:99

rħ

& FREE Returns

You can get up to 4% off on Amazon Business — and this past year, you would have saved 51 TIG 55 . Sign up, it's free. More details \sim . Get 5% back (\$11.99 in rewards) on the amount charged to your Amazon Prime Rewards Visa Signature Card. May be available at a lower price from other sellers, potentially without free Prime shipping.

Enhance your purchase

Payment plans

From \$40.00/mo (6 mo) with 0% APR



Fluke 289 True-RMS Stand Alone Logging Multimeter

Amazon's Choice for "fluke 289"

-12% \$71557

List Price: \$809.99 (1)

√prime

Û

& FREE Returns ~

or 12 monthly payments ~ of \$59.64

You can get up to 12% off on Amazon Business — and this past year, you would have saved \$ it's free. More details \curlyvee

May be available at a lower price from other sellers, potentially without free Prime shipping.

Style:

Fluke 289 True-RMS Logging Multimeter V

Brand	Fluke
Power Source	Corded Electric
Style	Fluke 289 True-RMS Logging Multimeter
Item Weight	1.92 Pounds
Item Dimensions LxWxH	0.24 x 0.4 x 0.87 inches

Roll over image to zoom in

Fluke 87V Digital Multimeter with a NIST-Traceable Calibration

\$55200

rh

√prime

& FREE Returns ~

Pay \$552.00 \$412.43 after using available Amazon Rewards Visa Card Points.

May be available at a lower price from other sellers, potentially without free Prime shipping.

Enhance your purchase

Payment plans

From \$30.67/mo (18 mo) with 0% APR

Brand	Fluke
Style	Fluke 87-V Multimeter w/ NIST Certificiate
Measurement Type	Multimeter

Images: Amazon





Roll over image to zoom in

Never use these cheap meters or connect to AC unless you know what you are doing - and even then avoid cheap meters!





YT Channel: DiodesGoneWild

Meter functions are marked with symbols on a dial or in a menu

Symbol	Meaning	Symbol
* v 🗔	V DC	* ++-
0		→
v	VAC	Hz
mV	millivolts (.001V or 1/1,000V)	$REL\Delta$
* Α mA μA	Amps milliamps (.001A or 1/1000A) microA (.000001A or 1/1,000,000A)	Range Hold 🚺 MIN MAX
* Ω	Resistance (Ohms)	
kΩ,ΜΩ *))))	kilo-Ohms, Megohms Continuity beeper	Λ

Meaning		
Capacitance	(uF: Microfarads)	
	(nF: Nanofarads)	
Diode test		
Hertz (cycles/sec)		
Relative or offset reading		
Manual override of autorange		
Touch Hold-last stable reading		
Highest, lowest recorded readings		
Dangerous vol	tage levels	
Caution: see r	manual	



Resistance Measurement

- Select the resistance function
- Plug black probe into COM jack and red into Ohms jack
- Touch probes across resistance to be measured, watch the units!
- OL is open circuit
- Testing a resistor in circuit works but it will always be better to measure the resistance in isolation.
 DO NOT MEASURE RESISTANCE
 ON A LIVE CIRCUIT!

Capacitance can be measured in a very similar way, however probing a capacitor that is in a circuit will have inaccurate results.





Image: electrical-engineering-portal.com

Voltage measurement is the most common task

- Select correct voltage function (AC/DC) Troubleshooting circuits:
- Plug black probe into COM jack and red into V jack
- Select highest range if the meter is not autoranging
- Touch probes across DUT in parallel to the voltage to be measured
- Use a Ground references

DO NOT:

Measure Battery voltage without a load

- Test power rails
- Test analog signals
- Test reference voltages



Image: electrical-engineering-portal.com


R

Current measurements require a different hookup structure

- Select the current function (AC or DC), use mA for small currents
- Ensure the circuit is powered off and break the circuit
- Insert the probes in series at the circuit break
- Plug black probe into COM jack and red into correct current jack
- Power the circuit

DO NOT:

- Try to measure voltage while in current mode
- Measure current without a load (Probe a Battery)





Pay attention to the mA/A connector - you may even need a current clamp device for higher current measurements










Continuity Beeper can be an incredibly useful tool!)))

- Identify pinouts of a cable
- Locate flakey connections
- Find shorts

In the event of a mishap in the lab, where a board sparks, shuts off, or pulls too much power, try buzzing out the board to identify if there are any shorts before powering on the device and testing voltages.



DO NOT CONTINUITY TEST A LIVE CIRCUIT!

